


## Building Structural Stability & Safety Certificate


I hereby certify that the school building of Krishna International Public School (managed by Hariprabhu Educational & Charitable Trust) situated in R. S. No. 281 At. Runi Po. Mandotri, Patan-Unjha Highway, Ta. & Dist. – Patan is constructed according to the plan approved and verified by Nagar Niyojak-Patan through No. NA/BP/Runi/1320 dt. 23/09/2016.

Certificate of structural stability and safety is also issued by Government Certified Structural Designer / Structural Engineer dt. 21/03/2018 .

I have inspected the School Building and found the building structurally stable and safe in all aspect for the educational institution.



  
**Deputy Executive Engineer**  
**R. & B. (Panchayat) Sub Division**  
**Patan**

  
**Executive Engineer**  
**R. & B. (Panchayat) Division**  
**Patan**




## Building Structural Stability & Safety Certificate


I hereby certify that the Canteen-cum-Auditorium Hall building of Krishna International Public School (managed by Hariprabhu Educational & Charitable Trust) situated in R. S. No. 281 At. Runi Po. Mandotri, Patan-Unjha Highway, Ta. & Dist. – Patan is constructed according to the plan approved and verified by Nagar Niyojak-Patan through No. NA/BP/Runi/1320 dt. 23/09/2016.

Certificate of structural stability and safety is also issued by Government Certified Structural Designer / Structural Engineer dt. 21/03/2018.

I have inspected the Canteen-cum-Auditorium Hall building and found building structurally stable and safe in all aspect for the educational institution.



  
**Deputy Executive Engineer**  
**R. & B. (Panchayat) Sub Division**  
**Patan**

  
**Executive Engineer**  
**R. & B. (Panchayat) Division**  
**Patan**